

Douglas County Road Funding Task Force

Douglas County Public Works
July 31, 2013


PCI Inspection




PCI vs. Repair Type




Pavement Life Cycle




Distribution of Pavement Area by Functional Classification



Area Weighted PCI (Last Inspection Date)




Road Maintenance Zones



- 1. Lake Tahoe
- 2. North County
- 3. Foothill
- 4. Johnson Lane
- 5. Minden/Gardnerville
- 6. Ranchos
- 7. South County


Distribution of Pavement Area



Distribution of Pavement Area

| Geographic Area | All Roads | Arterial | Collector | Local |
|-----------------|-----------|----------|-----------|-------|
| Foothill | 13% | 1 | 6% | 7% |
| Johnson Lane | 32% | 1 | 8% | 24% |
| Minden/GV | 30% | 1% | 12% | 17% |
| North County | 9% | 1 | 5% | 4% |
| Ranchos | 11% | 1 | 6% | 5% |
| South County | 2% | 1 | 1 | 2% |
| Lake Tahoe | 2% | 1 | 1% | 1% |
| Totals | 100% | 1% | 39% | 60% |


Summary of Pavement Condition (Last PCI Inspection)



Area-Weighted PCI by Geographic Area and Functional Classification (Last PCI Inspection)

| Geographic Area | All Roads | Arterial | Collector | Local |
|-----------------|-----------|----------|-----------|-------|
| Foothill | 63 | - | 52 | 72 |
| Johnson Lane | 74 | - | 73 | 74 |
| Minden/GV | 60 | 95 | 71 | 49 |
| North County | 65 | - | 71 | 56 |
| Ranchos | 47 | - | 50 | 44 |
| South County | 30 | - | - | 30 |
| Lake Tahoe | 72 | - | 80 | 61 |

Budget Analysis







Existing Conditions – PCI 10



Asphalt Zipper





First Pass



Zipped Material



Regraded Material





Application of Asphalt Emulsion








Finished Surface

Impact of Inflation on 1986 Gas Tax Based on ENR Construction Cost Index



Weighted Average Age at Inspection

